

00557 - A power switch cap

On 2024-05-26, a power switch cap fell down. To solve this issue, Anton took a drop of glue and fixed parts together! Fixed.

Revision #3

Created 28 May 2024 14:55:17 by Anton TETERIN

Updated 28 May 2024 15:43:36 by Anton TETERIN